


② 旧末広中学校の概況等

●外観・内装

<p>正面外観</p>  A photograph showing the front facade of a multi-story school building. The building is light-colored with numerous windows. A green awning is visible over the entrance area. The foreground shows a paved area and some greenery.	<p>グラウンド</p>  A photograph of an outdoor area, likely a sports field or playground. The ground is a mix of dirt and sparse grass. A tall green structure, possibly a goalpost or part of a sports facility, is visible on the right side. The background shows trees and a clear sky.
<p>校舎</p>  A photograph of the school building from a different angle, showing a side facade with many windows. The building appears to be made of concrete or a similar material. The sky is overcast.	<p>屋内運動場</p>  A photograph of a large, single-story building with a red roof, which is the indoor sports hall. It has a prominent chimney and large windows. A blue cart is parked in front of the building.
<p>校舎内</p>  A photograph of a long, brightly lit hallway inside the school building. The floor is polished and reflects the overhead lights. There are glass-walled rooms on both sides of the hallway.	<p>校舎内</p>  A photograph of the interior of the indoor sports hall. The floor is made of polished wood and has basketball court markings. The ceiling is high with exposed wooden beams and several hanging lights. Large windows are visible on the right side.

●敷地図面



<借用地>

赤い点線で囲った部分は、現在、国からの借地(国有地)となっています。

<除雪の状況>

隣接する市道高島線は、「連続した降雪があり、出勤の判断時に 15cm以上の降雪量が見込まれ、除雪作業が必要な時」などに、除雪車による除雪が行われています。

● 建物図面

